

CNC MACH breakout board user manual V8 type



Catalogue


CNC Router breakout board V8 type user manual **Ошибка! Закладка не определена.**

1) Brief introduction:	2
2) Breakout board drawing:	2
3) Wiring:	3
3.1、X、Y、Z、A、B axis connect with stepper motor driver wiring	3
3.2、Limit and E-stop wiring	3
3.3、Relay port.....	4
3.4、DB25 description	4
6、Mach3 software setting and usage:	5
6.1、MACH3 start:	5
6.2、Mach3 setting:	6
6.3、Mach3 limit setting:	8
6.3、G code run:	8

1、 Brief introduction :


- 1) It can connect with 5 stepper motor driver to control 5pcs stepper motor, and board with high speed optocoupler be safe work for controller
- 2) It is with 4 wire optocoupler limit port and can connect with normal mechanical switch, PNP 3 wires proximity switch and 2 wires proximity switch
- 3) with relay port can control the spindle turn on/off
- 4) the input voltage is 12-36VDC
- 5) it support mach3 and Ncstudio card connect
- 6) it can output 12VDC power supply

2、 Drawing :




3、 Wiring :

3.1、 X、 Y、 Z、 A、 B axis wiring



3.2、 Limit and E-stop wiring

Breakout board's LM1-LM4 according to the DB25 port P10-P13



2 wire proximity switch same as mechanical limit switch connect

3 wire PNP wiring: VCC connect 12V, control pin connect LM1-4, and GND connect GND

3.3、 Relay port

The relay port only can simple turn on/off the spindle,A and COM or B and COM as a switch as NO/NC

3.4、 DB25 pins definition




Fig 5.1

PIN1	PIN3	PIN2	PIN5	PIN4	PIN7	PIN6	PIN9	PIN8	PIN10
All axis EN	X axis DIR	X axis PU	Y axis DIR	Y axis PU	Z axis DIR	Z axis PU	A axis DIR	A axis PU	Limit 1
PIN11	PIN12	PIN13	PIN17	PIN16	PIN14	PIN18~25			
Limit 2	Limit 3	Limit 4	B axis DIR	B axis PU	Relay port	GND			

6、Mach3 software setting and usage :

6.1、MACH3 open :




图 1



When finish the install of MACH3,the desktop will be three artwork,click Mach3Mill as below:




Fig 2 MACH3 opened interface

6.2、Setting :

See Fig3, Open the PORT & PINS menu of config menu




Fig 3




Fig 4

Set up the circle 1 of Fig4 for the frequency which influence the stepper motor speed, then set up the circle 2 as below Fig 5 for PIN




Fig 5

6.3、 Limit port setting :

Click “input signal” to setting as below Fig 7




Fig 7

6.3、 G-code run :

Mach3 software itself with test G-code as below Fig8




Fig 8

Find your G code, then open as Fig 9:




Fig 9




Fig 10

You will see "RESET" flicker after open the G code, you can click it to stop flicker, then run the circle 2 "CYCLESTART"

In addition, if you need manual control, you can press the TAB of keyboard, the manual control interface as below Fig 11




Fig 11