

MD5

MD5-5
MD5-3

Power control unit
for 2/3 axes

Doc.No.211.226/DGB

MD5-5231.00

serial numbers:

GG54

MOTOR RACK 1	9000215
motor rack 2	9000992
motor rack 3	899966


Ident-Nr.:

Revisionsstand:

Edition: March 1988

Technische Dokumentation
Technical Documentation
Documentation Technique

BERGER LAHR



Die in dieser Druckschrift enthaltenen Informationen, technischen Daten und Maßangaben entsprechen nach sorgfältiger Überprüfung dem neuesten Stand zum Zeitpunkt der Veröffentlichung. Etwa dennoch vorhandene Druckfehler und Irrtümer können nicht ausgeschlossen werden.
Konstruktive Änderungen oder Abweichungen bleiben ausdrücklich vorbehalten.

The information contained in this publication, i.e. technical data and measurements, are the result of careful checking and reflect the latest information available prior to publishing. It is possible that printing or other errors may be found to be present. We reserve the express right to make structural amendments or changes.

Toutes les informations, données techniques et cotes contenues dans ce catalogue sont relatives à l'état actuel des développements. Elles sont données sauf erreur et omission. De plus, la firme se réserve tous les droits quant aux changements ou modifications qu'elle apporterait au matériel.

Date: Tue, 28 May 2002 15:40:44 -1000 (HST)
From: Chris Yamasaki <yamasaki@jach.hawaii.edu>
To: Erik Starman <e.starman@jach.hawaii.edu>
Subject: switches

Erik,

The switch settings are as follows:
(from left to right)

CGS4 middle rack: the dip switches are set with #1 to the right
#2,3 &4 to the left
For the potentiometers: First module is set to 1
Second module is set to 0
Third module is set to 4

Michelle rack: Image inject, extract, spare (2 modules installed)

Dip switches are set 1,3 to the right
2,4 to the left
Potentiometer is set to 0 for the modules

Michelle rack: Cal unit (3 modules)

Dip switches are 1,3 to the right
2,4 to the left

Potentiometers are all set to 0

Chris

TABLE OF CONTENTS

1	DESCRIPTION	1-1
1.1	General information	1-1
1.2	Structure and accessories	1-2
1.2.1	Structure	1-2
1.2.2	Standard accessories	1-3
1.2.3	Further accessories	1-3
1.3	Technical data	1-4
1.3.1	Dimensions and power rating	1-4
1.3.2	Type code	1-5
1.4	Technical description	1-6
1.4.1	Power supply module	1-7
1.4.2	Power control card D 380.1X	1-8
1.4.3	Power control card D 550.0X	1-9
1.5	Types of signals	1-10
1.5.1	Active-high signals for MD 5-X	1-10
1.5.2	Potential-free contacts	1-10
1.6	Effects of the signals	1-11
1.6.1	Function of the signal inputs and effect on the motor with MD 5-31	1-11
1.6.2	Function of the signal inputs and effect on the motor with MD 5-52	1-12
1.6.3	Static data of the signal inputs (optocoupler inputs)	1-13
1.6.4	Levels and effects of the signals	1-13
2	OPERATION	2-1
2.1	Installation	2-1
2.1.1	Cables	2-1
2.1.2	Mains connection	2-6
2.1.3	Motor connection	2-7
2.1.4	Power control card settings	2-9
2.1.5	Signal inputs/outputs	2-11
2.1.6	Installation of the unit	2-12
2.1.7	Check list	2-13
2.2	Operation	2-14
2.3	Terminology	2-15
2.4	Malfunctions	2-17
2.4.1	Check list CL1	2-17
2.4.2	Check list CL2	2-18
3	MAINTENANCE	3-1
3.1	Maintenance work	3-1
3.1.1	Replacing fuses	3-1
3.2	Replacing cards	3-1
3.2.1	Replacing the control card D 380.1X	3-1
3.2.2	Replacing the control card D 550.0X	3-1

1 DESCRIPTION

1.1 General information

The compact control unit MD 5-X controls BERGER LAHR 5-phase stepping motors. MD 5-X serves as a link between the external control units and the 5-phase stepping motor.

Fig. 1-1 shows the interrelation of the MD 5-X and the peripheral equipment.




Fig. 1-1 Control system with MD 5-X

External control unit, such as

- POSAB 2000
- Oscillator card D 538
- PLC " " *D638*

1.2 Structure and accessories

1.2.1 Structure

The MD 5-X is a 2- or 3-axle unit which incorporates the following assemblies:

- Power supply unit (M 011.07/08)
- Power control card (D 380.1X or D 550.0X)
- Motherboard D 560.30

Fig. 1-2 shows the rear view of the MD 5-X with the corresponding connections.




Fig. 1-2 Rear view of MD 5-X

1.2.2 Standard accessories

The standard accessories are delivered with the equipment.

The accessories for MD 5-5230.00 include:

Amount MD 5-XX20.00	Amount MD 5-XX30.00	Designation	Order no.
1	1	Grounding strip	H 6-920-6
1	1	Fuse 0.8 A	N 1- 636-
2	2	Fuse 6.3 A	N 1- 636-
2	2	Fuse 8.0 A	N 1- 636-
1	1	Fuse 12.5 A	N 1- 636-
1	1	Connector spring 20	N 4- 657- 3
1	1	Connector housing	N 4- 657-30
2	3	Connector lock	N 4- 673-158
22	33	Connector pin 1	N 4- 673-170*
2	3	Connector hood	N 6- 673-187
1	1	Plate T	211.15-00-38
1	1	Plate T	211.15-00-39
2	3	Coupling ring	211.15-00-45
2	3	Washer B	211.15-00-46
2	3	Washer B	211.15-00-47
4	6	Strain relief clamps	211.15-00-48
2	3	Washer B	211.15-00-49
2	3	Clutch disk	211.15-00-56
2	3	Coupling ring	211.15-00-57
4	6	Strain relief clamps	211.15-00-63
1	1	Screw driver	260.35-00-08
2	3	Connector pin 25	N 4-673-53
1	1	Manual	211.226/DGB

* Note: Tools of AMP Co.: - pliers order no. 169422-1
 - dismantling tool order no. 725840-1
 - spare tubes order no. 725841-1

1.2.3 Further accessories

The following accessories can be ordered separately:

Designation	Order no.
Signal cable, 12-wire	H2-928-30
Motor cable, 10-wire, 0.75 mm ²	H6-928-14
Motor cable, 10-wire, 1.5 mm ²	H6-928-26
Screw connections suitable for motor cable H6-928-26 and BERGER LAHR 5-phase stepping motors with terminal box	N9-750-51

BERGER LAHR 5-phase stepping motors as ordered by you.

1.3 Technical data

1.3.1 Dimensions and power rating

Dimensions	see fig. 1-3
Weight	21 kg
Device adaptable to the following mains voltages	120 VAC \pm 10% 220 VAC \pm 10% 240 VAC \pm 10%
Mains frequency	50 ... 60 Hz
Power consumption	max. 1300 VA
Power loss of MD 5-52XX of MD 5-31XX	max. 290 W max. 150 W





Fig. 1-3 Dimensions

1.3.2 Type code

The assemblies of the MD 5-X are evident from the type code. The individual figures have the following meaning:



1.4 Technical description

Figure 1-4 shows the block circuit diagram of the control unit MD 5-X.

The individual assemblies assume the following functions:

The power supply module M011.07/08 can be connected to the different mains voltages. This is accomplished by connecting straps in the mains connection. With the aid of the transformer and subsequent bridge rectification the DC-voltage for the stepping motor and the electronic circuits is generated.

The power control card controls the BERGER LAHR 5-phase stepping motor. Depending on the type of motor in use, either power control card D 380.1X (phase current up to 14A) or D 550.0X (phase current up to 2.8A) must be used (see 1.3 "Technical data").

The motherboard D 560 is the connecting card between the individual plug-in cards and the plug connections at the rear.




Fig. 1-4 Block circuit diagram


1.4.1 Power supply module

The power supply module M011.07/08 is connected to the mains voltage via the 20-pole mains connection.

Access to the primary fuse is provided at the back of the equipment.

Mains fuse for	MD5-52	MD 5-31
120 VAC	T12.5A	T10A
220 V/240 VAC	T6.3A	T5A

The secondary fuses are accessible after removing the front panel.




Secondary fuses	MD 5-52	ELECTRIC CIRCUIT	MD 5-31	ELECTRIC CIRCUIT
Si1	T0.8A	Electronics	T0.8A	Electronics
Si2	^{10A} _{250V} T8.0A	70V motor	T10A	35V motor
Si3	^{10A} _{250V} T8.0A	70V motor	T10A	35V motor

1.4.2 Power control card D 380.1X

1.4.2.1 Operational data

Operating voltage	24 - 36 VDC \pm 10%
Phase currents adjustable	0.2 - 1.4 A
Indication of readiness	LED green

1.4.2.2 Display and programming switches



1.4.2.3 Phase current (given in A)


I (A)	0.15	0.30	0.45	0.60	0.77	0.88	1.00	1.25	1.30	1.40
Position	0	1	2	3	4	5	6	7	8	9

1.4.3 Power control card D 550.0X

1.4.3.1 Operational data

Operating voltage	35 - 70 VDC
Phase currents adjustable	0.55 - 2.8 A
Indication of readiness	1 LED green
Indication of malfunctions	4 LEDs red

1.4.3.2 Display and programming switches



1.4.3.3 Phase current (given in A)

I (A)	0.55	0.70	0.85	1.00	1.15	1.30	1.45	1.60	1.75	1.90
Position	0	1	2	3	4	5	6	7	8	9

I (A)	2.05	2.20	2.35	2.50	2.65	2.80				
Position	A	B	C	D	E	F				

1.5 Types of signals

The following galvanically isolated signals are used for MD 5-X at the 25-pole connector.

1.5.1 Active-high signals for MD 5-X

For admissible input voltage refer to chapter 1.6.3.

Connector pin	Meaning
+ -	Polarity
4 17	ZERO CURRENT / BOOST
3 16	GATE
2 15	SENSE OF ROTATION NEG., POS.
1 14	PULSE

1.5.2 Potential-free contacts

The relay contacts may be used for indicating readiness or malfunctions.

Potential-free relay contact (changeover contact) $V = 30 \text{ VAC}/36 \text{ VDC}$
max. $I = 0.2 \text{ A}$
 $P = 5 \text{ VA}$

Connector pin	Meaning
9	9 - 22 closed - not ready
22	Switch contact
10	10 - 22 closed - ready

1.6 Effects of the signals

1.6.1 Function of the signal inputs and effect on the motor with MD 5-31

Signal input	Signal input current	Signal input no current	Switch position ^①
Pulse	upon current flow edge, the motor performs a step	in case of no current, the motor does not perform a step	
Direction ^①	CCW rotation	CW rotation	"OFF"
	CW rotation	CCW rotation	"ON"
Gate ^①	Pulse input blocked	Release pulse input	"OFF"
	Release pulse input	Pulse input blocked	"ON"

^① The effect of the direction and gate signal may be reversed by a sliding switch (see 2.1.4.2).




Fig. 1-5 Optocoupler input

1.6.2 Function of the signal inputs and effect on the motor with MD 5-52

Signal input	Signal input current	Signal input no current	Switch position 1 2
Pulse	upon current flow edge, the motor performs a step	in case of no current, the motor does not perform a step	
Direction 1	CCW rotation CW rotation	CW rotation CCW rotation	"OFF" "ON"
Gate	Pulse input blocked	Release pulse input	"OFF"
Zero current/boost 2	Phase current = 0 Phase current = $I_{nom} \times 1.2$	Adjusted phase current is valid	"OFF" "ON"

- 1 The effect of the direction and gate signal may be reversed by a sliding switch (see 2.1.4.2).
- 2 The zero current or boost function may be selected via a sliding switch (see 2.1.4.2).





Fig. 1-6 Optocoupler input

1.6.3 Static data of the signal inputs (optocoupler inputs)

MD5-5231

	MD 5-XXX0			MD 5-XXX1			MD 5-XXX2		
	min.	typ.	max.	min.	typ.	max.	min.	typ.	max.
Input voltage	20V	24V	30V	4V	5V	7V	TTL-push-pull level		
Input current		12mA	15mA		20mA	25mA		35mA	40mA
Input resistance		2000Ω			240Ω			100Ω	

1.6.4 Levels and effects of the signals



t1: Preparation time for direction signal	0 μs
t2: Hold time	5 μs
t3: Pulse duration	5 μs
t4: Pulse interval	5 μs
t5: Preparation time for gate signal	50 μs
t6: Response time of motor current to boost	30...100 μs
t7: Response time of motor current to zero current	100...300 μs

2 OPERATION

2.1 Installation

2.1.1 Cables

2.1.1.1 Recommended signal cables

BERGER-LAHR cable
Order no. H6-928-30

Signal cable for RS 422

Cross-section 0.24 mm² AWG 24
Screening: copper braiding with strand
Outside diameter 9.4 mm, PVC-sheating

Supplier: BERGER LAHR GmbH
Max. length delivered: 1000 m
Max. laid length: 300 m

Belden (US)

UL-approved signal cable
Type 9833 for RS 422

Cross section 0.25 mm² AWG 24
7 x 2 wires, twisted in pairs
Screening: copper braiding with strand
Outside diameter 9.4 mm, PVC-sheating

Supplier: Firma Elkab, 7700 Singen
Delivered lengths: 30.5 m - 152.4 m - 304.8 m
Max. laid length: 300 m

2.1.1.2 Recommended motor cable

Numbered cable by BERGER LAHR
Order no. H6-928-14

Cross-section 0.75 mm² (24 x 0,2)
5 x 2 wires twisted in pairs
Screening: copper braiding with strand 75 mm²
Outside diameter approx. 14 mm
PVC-sheating
Oil resisting

Supplier: BERGER LAHR GmbH
Max. length delivered: 1000 m

Numbered cable by BERGER LAHR
Order no. H6-928-26

Cross-section 1.5 mm² (30 x 0,25)
5 x 2 wires twisted in pairs
Screening: copper braiding with strand 0.75 mm²
Outside diameter approx. 16 mm
PVC-sheating
Oil resisting

Supplier: BERGER LAHR GmbH
Max. length delivered: 1000 m
Max. laid length: 100 m

The actual motor output depends on the cable length and cable cross-section.

ATTENTION


When laying other cables, the noise immunity may be reduced. Therefore make sure that the cable is screened and the wires are twisted in pairs.

2.1.1.3 Table for selecting the line cross-section

Cable length	Cable cross-section			
	0.75 mm ²	1.0 mm ²	1.5 mm ²	2.5 mm ²
10 m	0.46	0.34	0.23	0.14
25 m	1.15	0.86	0.58	0.34
50 m	2.30	1.72	1.15	0.69
100 m	4.60	3.45	2.30	1.38
Cable resistance R_L (Ω)				

The cables are to be selected according to the following criteria:

- The cable cross-section should not be less than 0.75 mm².
- The motor cable length should not be more than 100 m.
- The resistance of a line should not exceed the motor winding resistance.



$$R_L \leq R_W$$

R_L = Line resistance
 R_W = Winding resistance
 L_W = Winding inductance

Winding resistances of BERGER LAHR 5-phase stepping motors:

*

Type RDM	554/ 50	564/ 50	566/ 50	566/ 50H	569/ 50	569/ 50H	596/ 50	596/ 50H	599/ 50	599/ 50H	5913/ 50
$R_w \Omega$	5.0	2.5	4.0	1.4	2.3	0.85	2.1	0.43	3.5	0.7	1.0

Order no. of motor cable: H6-928-14 = 0.75 mm²

Order no. of motor cable: H6-928-26 = 1.50 mm²

Suitable screw connection: PG 16

Special version, order no.: n9-700-51

Example: RDM 5913/50 $R_w = 1.0 \Omega$

The maximum laid length of the cable H6-928-14 (cross-section = 0.75 mm²) is approx. 22 m.

The maximum laid length of the cable H6-928-26 (cross-section = 1.50 mm²) is approx. 45 m.

2.1.1.4 Laying of cables and interference suppression

In order to avoid interference the following must be observed:

- Lay motor cables and signal cables in different ducts.
When laying the cables in parallel it is recommended to keep a distance of at least 0.2 m.
- Lay the motor and signal cables at a proper distance to high-voltage current cables.
Recommended minimum distance is 0.2 m.
- Connect the ground stud M5 with low resistance at the rear of the unit via a copper braiding in order to achieve maximum interference immunity for the unit to observe the limit values of radio shielding according to VDE 0871 (complying with the limits for a class B device).

2.1.2 Mains connection

2.1.2.1 Jumper connection

The jumpers must be connected according to the mains voltage present (see fig. 2-1):




Fig. 2-1 Mains connection - soldering side

2.1.2.2 Mains fuse

The mains fuse at the rear of the unit must be checked with regard to the mains voltage present.

Mains voltage	MD 5-52 Nominal current of the fuse	MD 5-31 Nominal current of the fuse
120 VAC	T 12.5 A	T 10A
220 VAC	T 6.3 A *	T 5A *
240 VAC	T 6.3 A	T 5A

* provided ex works

2.1.3 Motor connection

2.1.3.1 Preparing the motor cable

The motor cable is to be prepared according to the following figure.





Fig. 2-2 Preparing the motor cable

2.1.3.2 Motor cable connection

The motor cable is to be connected to the connector and motor terminal box according to the following figure.



Motor version		Connector Pin
with terminal box Cable no.	with strand Colour	
0	violet	L
9	brown	K
8	black	J
7	grey	I
6	green	H
5	orange	G
4	red	F
3	blue	E
2	white	C
1	yellow	A

Motor windings = WI ... WV




Fig. 2-3 Motor cable connection

Rock 1	I	1 IROT	II	1 FIL1	III	3 FIL 2
Rock 2	I	1 CVF	II	1 SLIT	III	5 GRATING
Rock 3	I	1 TRANS	II	1 FOCUS	III	4 CAL

PHASE CURRENT
COLD SETTINGS
Feb 12 1992

2.1.4 Power control card settings

In order to set the values on the power control card the front panel must be detached (see "Technical data").

2.1.4.1 Motor phase currents

The phase currents have to be set with the rotary coding switch of the power control card D 380.1X or D 550.0X according to the type of stepping motor in use.

ATTENTION

The maximum nominal phase current must not be exceeded.


NOTE

The current can be set to a lower value, which results in a torque reduction approximately proportional to the phase current.

Rotary coding switch position D 380.1X	Type of stepping motor	Nominal phase current	Rotary coding switch position D 550.50
2	RDM 554/50	0.4 A	-
4	RDM 564/50 *	0.75 A	1
8	RDM 564/50H	1.3 A	5
4	RDM 566/50	0.8 A	1
8	RDM 566/50H	1.3 A	5
9	RDM 569/50	1.4 A	5
-	RDM 569/50H	2.3 A	B
8	RDM 596/50	1.25 A	4
-	RDM 596/50H	2.7 A	E
7	RDM 599/50	1.15 A	4
-	RDM 599/50H	2.4 A	C
-	RDM 5913/50	2.8 A	F

2.1.4.2 Programming functions

The toggle switches of the control card D 380.1X or D 550.0X allow programming different functions. It must be noted that the function of switch 1 is different on the two power control cards.



Switch 1: (invert gate on D 380.1X)

Switch position	OPEN	CLOSED
Signal input current	pulse input blocked	release pulse input
Signal input inactive	release pulse input	pulse input blocked

Switch 1: (zero current/boost on D 550.0X)

Switch position	OPEN	CLOSED
Signal input inactive	I_{nom} phase current	I_{nom} phase current
Signal input current	no current (zero-current mode)	$I_{nom} \times 1,2$ (boost mode)

Switch 2: (current reduction)

	OPEN		CLOSED	
Pulse frequency	< 10 Hz	> 10 Hz	< 10 Hz	> 10 Hz
Motor current I	I_{nom}	I_{nom}	$I_{nom} \times 0,7$	I_{nom}

Switch 3: (direction reversal)



Switch position	OPEN	CLOSED
Direction reversal	OFF	ON

Switch 4: (step angle)

Switch position	OPEN	CLOSED
Step angle	Full step 500 steps per rotation ($\alpha = 0,72^\circ$)	Half step 1000 steps per rotation ($\alpha = 0,36^\circ$)


2.1.5 Signal inputs/outputs

- Signal connector (3 x per axle 1...3), 25-pole "Sub-D", viewed from the soldering side
- Signal cable screening is effected on the transmitter side.



The relay contacts may be used for the indication of readiness or malfunctions.

- Block circuit diagram for internal relay contact




Technical data of the relay

V_{max}	-	30V
V_{max}	=	36V
I_{max}		0.2A
P_{max}		5VA

- 9 - 22 closed unit not ready
- 10 - 22 closed unit ready

The optocoupler inputs are designed for 24 VDC or 5 VDC or TTL-push-pull. The current is internally limited by pre-resistors.

- Block circuit diagram for optocoupler inputs



The "zero current or boost" function is not available for MD 5-31.

2.1.6 Installation of the unit

The possibilities of fastening the telescopic rails are evident in fig. 1-3.

2.1.6.1 Cooling the unit

When installing the unit ensure that:

- cool air is able to enter uninhibitedly at the front of the unit
- warm air is able to exit uninhibitedly at the rear of the unit.

	MD 5-52	MD 5-31
Ambient temperature	max. 50°C	max. 50°C
Motor phase current	max. 2.8A/phase	max. 1.4A/phase

2.1.7 Check list

Before starting the unit the following conditions must be fulfilled in order to ensure trouble-free operation.

Conditions	Details see
Has the equipment been set to the mains voltage present?	2.1.2
Is air able to enter and exit?	2.1.6
Has the right type of motor been installed?	
Have the signal and motor cables been laid at a proper distance to each other?	2.1.1
Has the signal connector been wired correctly?	2.1.5
Has the motor connector been connected correctly for all five phases? ATTENTION Never plug-in or remove the motor connector with the unit switched on (contact erosion owing to arcing).	2.1.3
Have the motor currents been set on the card D 380.1X/ D 550.0X according to the table? ATTENTION The maximum phase current of the 5-phase motor in use must not be exceeded.	2.1.4
Have the other switches on the card D 380.1X/D 550.0X been set correctly?	2.1.4

card may be damaged.

2.2 Operation

Upon applying the mains voltage, the MD 5-X is ready for operation and responds to the following control signals:

- Step angle
- Step frequency
- Sense of rotation
- Phase current

The following external digital control units may be connected for the generation of the control signals:

POSAB 2000
3-channel oscillator card D 538
1-channel oscillator card D 638
Processor control unit
PLC

2.3 Terminology

Explanation of terminology in alphabetical order:

Acceleration Hz/ms	Acceleration time of the stepping motor from the start/stop frequency to the maximum frequency set.
Boost	Temporary increase of the set phase current to $I_{\text{phase}} \times 120\%$. Observe the maximum permissible heating of the motor!
Clockwise rotation of SM	Positive rotation as seen from the motor shaft (flange side).
Counterclockwise rotation of SM	Positive rotation as seen from the motor shaft (flange side).
D 380.1X/D 550.0X	Constant-current control card for a BERGER LAHR 5-phase stepping motor.
D 538	Oscillator card for setting the frequencies, acceleration and deceleration
<i>2638</i> Delay time t_f	Period of delay of the SM from the maximum frequency set to the start/stop frequency.
Excessive temperature	The maximum permissible temperature is exceeded.
Fall time t_f	Duration of the falling signal edge.
5-Phase-stepping motor (5-phase-SM)	Refer to BERGER LAHR prospectus No. 350.
Full step	On 5-phase-SM this means 500 steps/revolution corresponding to $0.72^\circ/\text{step}$ i.e. double the step angle of half step.
Gate	Pulse input can be disabled with this function.
Half step	On 5-phase-SM this means 1000 steps/revolution corresponding to $0.36^\circ/\text{step}$, i.e. the step angle is halved compared with full step operation.
Hold time t_h	Minimum time a direction or other signal is waiting to be served after the active pulse edge
Overload	The permissible current of the control card is exceeded.
Overvoltage	The nominal voltage exceeds the permissible tolerance.
Phase current	The current which flows through one winding of the SM.
Pulse duration t_p	The time span of one pulse waiting to be served.

Revolutions min ⁻¹	Calculated from step frequency x $\frac{\text{step angle} \times 60}{360^\circ}$
Rise time t _r	Duration of the rising signal edge.
Setup time t _{su}	Minimum time a direction or other signal is waiting to be served before the active pulse edge.
SM	Stepping motor
Start-/stop frequency	Maximum control frequency with which the motor can start and stop safely without stepping errors with a certain load, consisting of friction and acceleration of rigidly connected centrifugal masses.
Step	Process in which the motor shaft of the SM executes a movement corresponding to one step angle.
Step angle in degrees	The nominal angle through which the motor shaft of the SM rotates per each control pulse.
Step frequency f _s in steps/s	Number of steps executed by the motor shaft of the SM in one second on constant control frequency.
Undervoltage	The nominal voltage falls short of the permissible tolerance.
Zero phase current	Motor is not supplied with current - no holding moment.

2.4 Malfunctions

2.4.1 Check list CL1

Malfunctions without error message	Possible cause	Recommended action to eliminate the error
Motor does not start	Incorrect signal connection	Check signal connection
	Electric equipment does not work properly	Check electric equipment
Motor does not perform the desired function	Incorrect switch position on D 380.1X/D 550.0X	Check switch position on D 380.1X/D 550.0X
	Start-stop frequency too high	Set start-stop frequency to a lower value
Motor does not start	Acceleration ramp too steep	Set the acceleration ramp in the control circuit to a lower value
	Driven load too sluggish	Check driven load:
		- ensure easy running
		- adapt driven load
Motor does not reach the required maximum frequency	- reduce the required max. frequency	
	Built-in motor type is not suitable	- choose a more powerful motor
Motor does not run smoothly	Motor cable defective	Check motor cable
	Motor defective	Replace motor
	Power amplifier defective	Replace power amplifier
Positioning error	Incorrect control signals	Check signal control

2.4.2 Check list CL2

For diagnosis and elimination of errors on the D 380.1X card the following applies:

- o green LED = operative
- o red LED = malfunction

For diagnosis and elimination of errors on the D 550.0X card the following applies:

- 1 green o - card ready
- 2 red o - overload
- 3 red o - excessive temperature
- 4 red o - under-/overvoltage
- 5 red o - phase interruption

Error message	Possible cause	Recommended action to eliminate the error
No LED lights up	Mains fuse defective	Check fuses
	Malfunc. in the power supply unit	
LED 2 lights up	Motor wrongly connected	Check motor connection
	Cable defective	Check cable
	Motor defective	Check motor
	A strong disturbing pulse has occurred	Observe distance between the cables
LED 3 lights up	Ambient temperature too high Ventilation adequate?	Make sure that air can enter and exit uninhibitedly
LED 4 lights up	Mains voltage too high/ too low?	Check mains connection
	D 550.0X defective?	Replace D 550.0X
LED 5 lights up	Wire break in the motor cable Cold soldering joint at motor cable or connector	Check motor connection

3 MAINTENANCE

3.1 Maintenance work

Depending on the degree of air pollution: - Check air filter mat on the front panel periodically
 - Replace if very dirty

3.1.1 Replacing fuses

The primary fuse can be accessed at the rear of the equipment.

Mains fuse for	MD 5-52	MD 5-31
120 VAC	T12.5A	T10A
220 V/240 VAC	T6.3A	T5A













3.2 Replacing cards

3.2.1 Replacing the control card D 380.1X

After having replaced the control card D 380.1X, verify before switching it on again that the rotary switch position and the sliding switch position correspond with the type of stepping motor in use.

3.2.2 Replacing the control card D 550.0X

After having replaced the control card D 550.0X, verify before switching it on again that the rotary switch position and the sliding switch position correspond with the type of stepping motor in use.

Rotary switch position D 380.1X	Type of stepping motor	Nominal phase current	Rotary switch position D 550.0X
 2	RDM 554/50	0.4 A	-
 4	RDM 564/50	0.75 A	1
 8	RDM 564/50H	1.3 A	5
 4	RDM 566/50	0.8 A	1
 8	RDM 566/50H	1.3 A	5
 9	RDM 569/50	1.4 A	5
 -	RDM 569/50H	2.3 A	B
 8	RDM 596/50	1.25 A	4
 -	RDM 596/50H	2.7 A	E
 7	RDM 599/50	1.15 A	4
 -	RDM 599/50H	2.4 A	C
 -	RDM 5913/50	2.8 A	F

NOTE
 Mark switch positions set.

TABLE OF FIGURES

Fig. 1-1	Control system with MD 5-X	1-1
Fig. 1-2	Rear view of MD 5-X	1-2
Fig. 1-3	Dimensions	1-4
Fig. 1-4	Block circuit diagram	1-6
Fig. 1-5	Optocoupler input	1-11
Fig. 1-6	Optocoupler input	1-12
Fig. 2-1	Mains connection - soldering side	2-6
Fig. 2-2	Preparing the motor cable	2-7
Fig. 2-3	Motor cable connection	2-8

INDEX

A	
Accessories, standard	1-3
Active-high signals	1-10
B	
Boost	1-9, 2-10
C	
Cable	1-3, 2-2
Cable cross-section	2-3
Check list	2-13, 2-17
Class	1-5
D	
D 380.1X	2-9
D 538	1-14, 2-15
D 550.0X	2-9
D 560.30	1-2
D 638	2-15
Delay time	1-13
Device type	1-2
Dimension	1-4
Direction	1-11
Display	1-8, 2-9, 2-15
E	
External operation	2-11, 2-14
External supply voltage	2-11
F	
Fall time	1-13, 2-16
Full step	2-10
Fuses	1-7
G	
Gate	1-12
H	
Half step	2-10
Hold time	1-3, 2-15
I	
Interference suppression	2-2, 2-5
Internal operation	2-14
L	
Line resistance	2-3

M	
Mains connection	2-6
Malfunctions	2-17
Motherboard	1-6
Motor cable	2-7
O	
Operating voltage	1-7, 2-6
Optocoupler	2-11
Oscillator card	2-14
Overload	2-15
Overvoltage	2-15
P	
Phase current	2-15
Phase current, nominal	2-9
PLC	2-14
POBAB	2-14
Positioning control	2-14
Potential-free contacts	2-11
Power consumption	1-4
Power control card	1-8
Power supply module	1-6
Programming switch	2-10
Pulse	1-10
R	
Relay contacts	2-11
Replacing cards	3-1
Replacing fuses	3-1
Response time	1-13
Rise time	1-13, 2-15
S	
Screw connections	1-3, 1-4
Setup time	1-13, 2-15
Signal cable	2-1
Signal input	1-10
Signal voltage	1-10
Speed	2-10
Step frequency	2-10
Stepping motor, type of	2-4, 2-9
T	
Type code	1-5
U	
Undervoltage	1-13, 2-17
V	
Voltage	2-6
Variants	1-5

W

Weight

1-4

Winding inductance

2-3

Winding resistance

2-3, 2-4

Z

Zero current

1-12

BERGER LAHR GmbH

Breslauer Str. 7
Postfach 1180

D-7630 LAHR

**Proposals
Improvements**

MD 5-X device documentation

Power control unit
for 2/3 axles

Edition: March 1988
Doc.no. 211.226/DGB

Sender:

Name:

Company/department:

Address:

Telephone no.:

Please inform us, using this form, if you have discovered any printing errors when reading this document. We should also appreciate any new ideas and proposals.

Proposals and/or improvements

Sprechen Sie mit Ihrem BERGER LAHR-Fachberater! Talk to your BERGER LAHR technical consultant! Consultez nos experts en technique de commande!



Technisches Büro Nord
Ing. (grad.) H. P. Meyer,
Moorweg 21, 3107 Hambühren
Ortsteil Oldau,
Tel. 05143/6585 · Telex 925297
Telefax 05143/2265
Zuständig für die Postleitzonen
1, 2 und 3 (außer 35)

Technisches Büro West
Dipl.-Ing. J. Polgar
Westerbergstr. 13, 5963 Wenden 1
Tel. 027 62/2781 · Telex 876637
Telefax 027 62/3739
Zuständig für die Postleitzonen
4 und 5 (außer 54 und 55)

Technisches Büro Mitte
G. Püschel
Nordring 29, 8751 Eisenfeld
Tel. 06022/8761 + 7553
Telex 4 188410
Telefax 06022/7909
Zuständig für die Postleitzone 6
(+ 35, 54, 55 und 87)

**Technisches Büro
Baden-Württemberg**
Dipl.-Ing. (BA) G. Klemm
und S. Stiller
BERGER LAHR GmbH
Breslauer Str. 7, 7630 Lahr
Tel. 07821/582-412 + -283
Telex (17) 782119
Telefax 07821/582313
Zuständig für die Postleitzone 7

Technisches Büro Bayern
J. Huber und V. Freienthner
Salmdorf 2, 8013 Haar
Tel. 089/4392123 + 24
Telex (17) 896076
Telefax 089/4392978
Zuständig für die Postleitzone 8
(außer 87)



NV I.C.A. SA
Verbindungslaan 2
B-9090 Kemzeke
Tel. 32-37796821
Telex NV ICA SA (B) - 35679
Telefax 0032/37796827



H. & K. Lübcke Holding ApS
Jernbane Allé 43
DK-2720 Kobenhavn/Vanlose
Tel. 01-743322
Telex 02381 117 881
Telefax 00451743377



Osakeyhtiö Sähkökonttori AB
Särkiniementie 5 B
SF-00210 Helsinki 21
Tel. 673087 · Telex 124 825
Telefax 00358/06924387



BERGER LAHR S.à.r.l.
5, Rue Charles Michels
F-95102 Argenteuil
Tel. (1) 39.80.60.26
Telex 609299, Telefax 1398278 15



BERGER LAHR UK Ltd.
Unit B 2, Deseronto Estate
St. Mary's Road, Langley,
Slough, Berks. SL3 7EW
Tel. 0753-41613 · Telex 848950
Telefax 0753-581524 (Gp 2 & 3)



BERGER LAHR AG
Pestalozzistr. 11
CH-9400 Rorschach
Tel. 071/414771 · Telex 882917
Telefax 0041/71410647



BERGER LAHR S.r.l.
Via Aurelio Saffi, 23
I-10138 Torino
Tel. 11/44.36.36/37/38
Telex 224254
Telefax 114476298



PAGE INDIA LTD.
1009, TVS Colony
Anna Nagar Western Extension
Madras 600101 - INDIA
Tel. 0091-44-654525
Telefax 0091-44-866827



Giken Shoji Co., Ltd.,
2nd Floor, Marukoshi Bldg.,
6-5, 4-Chome, Sakae, Naka-Ku,
Nagoya, Japan 460
Tel. 052/251-4721
Telex 4422518 GIKEN J
Telefax 052/251-0229



BERGER LAHR Corporation
Fitzgerald Drive
P.O. Box
Jaffrey N. H. 03452
Tel. (603) 532-7701
Telex 92-8445
Telefax 6035326077



ELECTRO ABi B.V.
Aandrijf- en Besturingstechniek
A. Hofmanweg 60
NL-2031 BL Haarlem
Tel. (023) 319292 · Telex 41183
Telefax 003123-326599



BERGER LAHR Ges. mbH
Jedleseerstr. 108
A-1210 Wien
Tel. 0222-387545
Telex 135738 (Panel a)
Telefax 0043/22238754433



BERGER LAHR AB
Sabelgatan 4
S-25266 Helsingborg
Tel. 42-162230 · Telex 72294
Telefax 42160035



Forn Valls S.A.
Milanesado no. 2-tda.
08017 Barcelona
Tel. (93) 2034133 + (93) 2040544
Telex 52491



Finex-Handels GmbH
Erzgießereistr. 24
8000 München 2
Tel. 089/527011 · Telex 5-24306
Telefax 089/526250



Bochako-Technik, Valentinskamp 18
2000 Hamburg 36
Tel. 040/34106-0 · Telex 212435
Telefax 040/34106-245



WTC GmbH
Kennedy-Allee 78
6000 Frankfurt/Main 70
Tel. 069/6311077-79
Telex 414836
Telefax 069/634016

Wir machen Bewegung We make things move Commande de tous mouvements

Wer rastet, rostet. Durch intensive Forschung und Weiterentwicklung unserer Produkte haben wir Fakten in der Motoren-Technologie geschaffen, die uns von den Wettbewerbern abheben.

Steuerungselektronik, Mikroprozessoren, modernste Schrittmotoren-Technologie führen auf den Weg zur Systemlösung.

Wir liefern Systemlösungen.

Wir machen Bewegung für Ihren Erfolg.

With innovative ideas BERGER LAHR strives to be always at the forefront of progress. As a result of many years of intensive research and development we have become a leader and trendsetter in motor technology, and with our products



and system solutions we are keeping our nose in front of the competition. Our microprocessor-controlled electronic drive units and modern stepping motor technology are the essential components for individual system solutions – the key to our and your success.

Avec son esprit innovateur BERGER LAHR s'efforce d'assurer la capacité compétitive par la mise au point d'excellents produits et de solutions systématiques qui déterminent les tendances dans la technologie des moteurs. Nous devons notre position d'avant-garde aux recherches intensives et aux efforts investis dans le développement de nos produits.

L'électronique de commande avec microprocesseurs et une technologie d'avant-garde des moteurs pas à pas représentent un complément logique dans nos efforts de résoudre des problèmes de commande de toute nature.

Nos solutions systématiques et individuelles garantissent le progrès et votre succès.

Das BERGER LAHR Lieferprogramm: BERGER LAHR Delivery Programme: Programme de livraison:

Synchronmotoren
Getriebemotoren
Stellantriebe
2-Phasen-Schrittmotoren
5-Phasen-Schrittmotoren
Leistungsansteuerungen für Schrittmotoren
Positionier- und Ablaufsteuerungen
Linearmodule

Systemlösungen für vielfältige Automatisierungsaufgaben.

Synchronous motors
Geared motors
Positioning motors
2 Phase stepping motors
5 Phase stepping motors
Power drives for stepping motors
Positioning and sequence control units
Linear Drive Modules

System solutions for various automation tasks.

Moteurs synchrones
Moteurs réducteurs
Moteurs de positionnement
Moteurs pas à pas 2-phases
Moteurs pas à pas 5-phases
Commandes de puissance pour moteurs pas à pas
Commandes de positionnement et commandes séquentielles
Modules d'entraînement linéaire

Solutions systématiques des problèmes de l'automatisation de toute nature.

BERGER LAHR

BERGER LAHR GmbH · Breslauer Str. 7, D-7630 Lahr
Postfach 1180 · Telefon (078 21) 582-0 · Tlx 17-782 119

 Ein Unternehmen der SIG Firmengruppe