



TB6560-T3 CNC Driver Manual

1. General introduction

Low noises and low vibration due to the using of the 16 excitation two-phase bipolar stepping motor driver chip TB6560AHQ imported from Japan. The electric circuit is well-designed. All the electric items have been strictly checked to insure the quality.

2. Specification

- rated voltage: DC12-DC30V;
- Single-chip motor driver for sinusoidal microstep control of stepping motors
- Forward and reverse rotation
- Selectable phase excitation modes (2, 1-2, 2W1-2 and 4W1-2)
- High output current: IO_{UT} = AHQ: 3.5 A (peak)
- Thermal shutdown (TSD)

If you need 36v power pls contact us.

3. Advantages

3.1 one power only

The control parts and the driving parts share one power. Users don't need any more power.

3.2 adjustable electric current

The out-put current can be adjusted according to user's needs.

3.3 well-arranged ports

A: The X port、the Y port and the Z port are connected to one port (3.96mm), which is very convenient for users to arrange the circuitry.

B: The stop signal input-port is connected to one port (3.96mm), which is very convenient for users to arrange the circuitry.

3.4 manual-control function

Users can manually control the drive board through a standard port which has 15 pins

3.5 the 4th axis can be added

Through a standard port which has 15 pins, the 4th axis can be added to the drive board according to users' needs.

3.6 protection of the computer

By using the isolating power(1000V DC\DC) and the optoelectronic coupler, the drive board are separated from the computer. Such design can protect user's computer in case the board are going abnormal.

3.6 protection of the drive board


The electric current of the drive board is locked to half of the normal one when no signals are received from the computer, thus the service life of the drive board is assured with less heat.

3.8 good-cooling function

All the items are fixed in a aluminium box which has good performance of the abstraction of heat to ensure the service life.

4. Configuration and pictures of the items





5. Ports

5.1 DB25 LPT pin define:

- 1 : the 2nd output control (corresponding circuitry pls see RY2 on the board, for electric relay or PWM OC output control, output current=50mA, voltage=24V)
- 2 : X axis pulse input
- 3 : X axis direction setting
- 4 : Y axis pulse input
- 5 : Y axis direction setting
- 6 : Z axis pulse input
- 7 : Z axis direction setting
- 8 : extending axis pulse input
- 9 : extending axis direction setting
- 10: LPT input signal 1 (corresponding IN1 on the board)
- 11: LPT input signal 2 (corresponding IN2 on the board)
- 12: LPT input signal 3 (corresponding IN3 on the board)

- 13: LPT input signal 4 (corresponding IN4 on the board)
- 14: NC
- 15: LPT input signal 5 (corresponding IN5 on the board)
- 16: all axis enable input
- 17: the 1st circuitry output control (corresponding RY1 on the board, for electric relay or PWM OC output control, output current=50mA, voltage=24V)
- 18: GND
- 19: GND
- 20: GND
- 21: GND
- 22: GND
- 23: GND
- 24: GND
- 25: GND

5.2 Manual control ports and definition

Input signal=0-5V

- 1 : X axis pulse input
- 2 : X axis direction setting
- 3 : Y axis pulse input
- 4 : Y axis direction setting
- 5 : Z axis pulse input
- 6 : Z axis direction setting
- 7 : all axis enable input
- 8 : the 1st circuitry output control (corresponding to RY1, for electric relay or PWM OC output control, output current=50mA, voltage=24V)
- 9 : extending axis pulse output
- 10: extending axis direction output
- 11: extending axis enable output
- 12: the 1st circuitry input control
- 13: 5V power , 20mA
- 14: Direct connecting to IN1
- 15: Power GND

5.3 power port

Power:12-24V

Current:10A

Pls see the picture for reference.

up: power GND

Down: power 12-24V

5.4 port for extending

From up to down:

- 1、IN1
- 2、IN2
- 3、IN3
- 4、IN4
- 5、IN5
- 6、GND
- 7、RY1
- 8、RY2
- 9、+5V
- 10、GND

6. Subdivision surface mode setting

	S5	S6
1	1	1
1/2	1	0
1/8	0	0
1/16	0	1

7. Decay mode setting

	S7	S8
NO DECAY	1	1
SLOW DECAY	1	0
MID DECAY	0	1
FAST DECAY	0	0

Notes: if the drive board has abnormal noise under working or locking condition, you can solve the problem by adjusting the decay mode.

8. Current adjusting and default testing

	S1	S2	S3	S4
20%→>20%	0	0	1	1
50%→>20%	0	1	0	1

75%-->20%	0	0	1	0
75%-->50%	1	0	0	0
100%-->20%	0	1	0	0
100%-->50%	0	0	0	0


Explanation:

EXAMPLE: 75%-->20%

Working Current=3.5A *75%


Pause current=3.5A *20%

9.How to use MACH software?




Pic.1

See Pic.1: open MACH3, choose Mach3mill,click OK.




Pic.2

See the Pic.2 for reference, there are common use buttons.



Pic.3


See Pic.3 ,open config-----ports and pins



Pic.4


CIRC1: frequency setting ,to control the speed

CIRC2: pls see Pic.5 for reference




Pic.5

Pls set the X\Y\Z\ axis as Pic.5 shows.



Pic.6

Choose "output signals" and then set as Pic. shows.



Pic.7


Impulse width setting:

Step impulse: 5us


Direction impulse: 5us

See Pic.7 for reference


Pls click "load G-code", see Pic.8 and Pic.9



Pic.8




Pic.9



Pic.10

After open the G-code, the reset light is blinking which means you are in stop condition. You can solve it by clicking the reset button(see circle 1), then click circle 2 to start “Cycle-start”.

If you needs manual control , pls click TAB button (see Pic.11)



Pic.11

10. Notes

Pls make sure that the drive board is under the rated temperature after working inconsistently for half an hour. If not pls contact us for help.

11. Contact us



SCOOB.NET: <http://www.scoob.net/>
 E-mail: info@scoob.net
 Phone: +31 653 454 999